

# CHARLES L. GIDEON ELEMENTARY SCHOOL

Weekly Construction Progress Report Week 4/22/19-4/26/19



**Balfour Beatty** 

#### 4/15/19-4/19/19 Activities

- Interior masonry walls at new building
- One sided interior drywall at lower level of new building
- Installing interior wall framing at upper level of new building
- MEP rough at new building
- Installed exterior metal panel brick cap flashing
- Installed window frames and glass at new building
- Installed exterior HM doors at new building
- Installed binder and asphalt at parking lot
- Started up Air Handler Units at renovation building
- Installing final paint at renovation building
- Installing epoxy flooring at renovation restrooms











**Balfour Beatty** 

## 4/15/19-4/19/19 Activities



The Kindezi School



HVAC, Framing, & Shaft Wall



Interior Framing & MEP Rough at Upper Level



**HVAC Floor Penetrations** 



Final Paint at Renovation



Shaft Wall, Door Frames, & Framing



Paint at Classrooms Renovations



## 4/15/19-4/19/19 Activities









Binder & Asphalt installed at Parking Lot

- Completed interior CMU walls at new building
- One sided interior gyp. bd. at lower and upper level of new building
- · MEP in wall rough at new building
- · Tied in Air Handling Unit at Kitchen/Cafeteria
- Installed Kitchen Exhaust Hood
- Started installing metal panel at Kitchen/Cafeteria
- Installing window frames and glass at new building
- Installing final paint at renovation building
- Completed epoxy flooring at renovation restrooms
- Started floor prep for VCT at renovation building
- Installing framing and gyp. bd. stage at Auditorium











**Balfour Beatty** 





Window Frame & Glass at Courtyard



Can Wash CMU Wall & Metal Panels



Single Side Gyp. Board, MEP In Wall, & Door Frames



els MEP Shaft Wall



Interior side of Windows



**Balfour Beatty** 












CMU Walls at Kitchen, Kitchen Exhaust Hood, & HVAC Tie-In to AHU



Stage Framing at Auditorium



Epoxy Flooring at Reno Restrooms



Final Paint at Reno Building



- Inspect MEP in wall rough at new building
- Start two siding gyp. bd. walls at new building
- Install window frames and glazing
- Continue installing metal panels at exterior of new building
- Complete gas piping
- Start ceramic tile at renovation restrooms
- Complete final paint at renovation
- Start VCT flooring/prep at renovation
- Installation of doors

# **Project Schedule**

- Project schedule impacted by delayed LDP and Building Permit procurement
- Project substantial completion: 8/1/19 per 2/12/19 schedule update
  - Execution of OCO 1 and OCO 2 adjusted substantial completion date to 8/1/19

# **Project Financials**

Current contract value: \$14,400,000.





